





**MoniServ, Inc**

<http://www.MoniServ.com>

<http://www.lcdpart.com>


## Backlight Inverter Installation Procedures for Dell 1701FP







Original Backlight Inverter board showed Photo.



Disconnected 4 backlight connectors. Replace with MoniServ SIC1802MSS. Re-install all component, metal chassis, circuit board and back cover. Dell 1701FP should work now.