



MoniServ Inc



<http://www.moniserv.com>


<http://www.lcdpart.com>

<http://www.monitoronsale.com>

Backlight Inverter Installation Procedures for NEC LCD1830







Disconnected 4 backlight connectors and Connector from AD Board. Replace with MoniServ UHP061104MSS Inverter board. Re-install all component, metal chassis, circuit board and cover back. NEC LCD1830 should work now.